Message (Digitally Signed)

From: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) [elizabeth.roddy@navy.mil]

Sent: 4/29/2021 12:07:54 AM

To: Han, Terry@CDPH [terry.han@cdph.ca.gov]; Praskins, Wayne [Praskins.Wayne@epa.gov];

juanita.bacey@dtsc.ca.gov

CC: Stoick, Paul T CIV USN NAVFAC SW SAN CA (USA) [paul.stoick@navy.mil]; Robinson, Derek J CIV USN NAVFAC SW

SAN CA (USA) [derek.j.robinson1@navy.mil]; Liscio, Matthew P CIV USN NAVSEA DET RASO VA (USA)

[matthew.liscio@navy.mil]

Subject: RE: N62473-17-D-0006 CTO: N6247318F5065 Parcel G - Soil Data Package TU-107

Attachments: smime.p7s

Terry,

To confirm there are 27 complete RSY pad packages to date. As of today, you should all have 26 of them.

There are currently 46 RSY pad lifts with material at the site.

- Twenty-seven (27) of those pads are complete, and the packages have been submitted to the Navy
- Two (2) of the RSY pads have Sr-90 exceedances, and need to be remediated and bounding samples collected.
 We have discussed these in the weekly meetings. Data packages will be available once bounding samples have been collected and analyzed. This is pending remobilization.
- One (1) RSY pad needs the static measurements collected. This is pending remobilization.
- Sixteen (16) RSY pads are in progress, not full, and/or not radiologically processed

Very Respectfully,

Liz Roddy Remedial Project Manager NAVFAC BRAC PMO West 33000 Nixie Way Bldg. 50, Floor 2 San Diego, CA 92147 (619) 524-5755 elizabeth.roddy@navy.mil

From: Han, Terry@CDPH <Terry.Han@cdph.ca.gov>

Sent: Wednesday, April 28, 2021 12:33 PM

To: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) <elizabeth.roddy@navy.mil>; Praskins, Wayne

<Praskins.Wayne@epa.gov>; Bacey, Juanita@DTSC <Juanita.Bacey@dtsc.ca.gov>

Cc: Stoick, Paul T CIV USN NAVFAC SW SAN CA (USA) real.stoick@navy.mil>; Robinson, Derek J CIV USN NAVFAC SW SAN CA (USA)

<matthew.liscio@navy.mil>

Subject: [Non-DoD Source] RE: N62473-17-D-0006 CTO: N6247318F5065 Parcel G - Soil Data Package TU-107

I got those 4 reports, R11U2, R11U3, R40U1, and R40U2 from you this morning. Thank you very much, Liz.

Thanks also for the summary on the data packages.

Does it mean that there were in total 27 lifts excavated from Parcel G before APTIM's pause a few months ago?

Thanks,

Terry

From: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) <elizabeth.roddy@navy.mil>

Sent: Wednesday, April 28, 2021 12:12 PM

To: Han, Terry@CDPH <Terry.Han@cdph.ca.gov>; Praskins, Wayne <Praskins.Wayne@epa.gov>; Bacey, Juanita@DTSC

<Juanita.Bacey@dtsc.ca.gov>

SAN CA (USA) <derek.j.robinson1@navy.mil>; Liscio, Matthew P CIV USN NAVSEA DET RASO VA (USA)

<matthew.liscio@navy.mil>

Subject: RE: N62473-17-D-0006 CTO: N6247318F5065 Parcel G - Soil Data Package TU-107

EXTERNAL EMAIL. Links/attachments may not be safe. To report suspicious emails, click "Report Phish" button.

Terry,

Thanks for confirming your receipt of the data packages. The list below is correct. In addition to this list I sent out 4 more data packages this morning which include: R11U2, R11U3, R40U1, R40U2.

In total I have 6 pending reports to submit to you all and then you will have everything we have received to date. This would total 27 reports. Until we remobilize in May and begin collecting samples again there are no further reports available.

Let me know if you have any further questions.

Very Respectfully,

Liz Roddy Remedial Project Manager NAVFAC BRAC PMO West 33000 Nixie Way Bldg. 50, Floor 2 San Diego, CA 92147 (619) 524-5755 elizabeth.roddy@navy.mil

From: Han, Terry@CDPH <Terry.Han@cdph.ca.gov>

Sent: Wednesday, April 28, 2021 11:23 AM

To: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) < elizabeth.roddy@navy.mil; Praskins, Wayne

<Praskins.Wayne@epa.gov>; Bacey, Juanita@DTSC <Juanita.Bacey@dtsc.ca.gov>

Cc: Stoick, Paul T CIV USN NAVFAC SW SAN CA (USA) < paul.stoick@navy.mil>; Robinson, Derek J CIV USN NAVFAC SW SAN CA (USA) < paul.stoick@navy.mil>; Robinson, Derek J CIV USN NAVFAC SW

SAN CA (USA) <<u>derek.j.robinson1@navy.mil</u>>; Liscio, Matthew P CIV USN NAVSEA DET RASO VA (USA)

<matthew.liscio@navy.mil>

Subject: [Non-DoD Source] RE: N62473-17-D-0006 CTO: N6247318F5065 Parcel G - Soil Data Package TU-107

Hi Liz,

Thank you for sending over these data packages, especially you resending the files individually due to the limitation of attachment file size.

In total, I have received the revision of 11 data packages (RSY18Use1 [R18U1], R20U2, R29U2, R20U3, R1U1, R1U2, R11U1, R12U1, R15U2, R29U1, R31U2) and 6 new data packages (R31U1, R30U1, R32U1, R35U1, R35U2, R38U10). Please let me know if this list looks correct to you.

In addition, do you know how many lifts are there on each RSY pad currently and how many data packages we have not received among those lifts?

Thank you very much!

Best,

Terry

From: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) <elizabeth.roddy@navy.mil>

Sent: Tuesday, April 27, 2021 3:33 PM

To: Praskins, Wayne < Praskins. Wayne@epa.gov>; Bacey, Juanita@DTSC < Juanita.Bacey@dtsc.ca.gov>; Han,

Terry@CDPH <Terry.Han@cdph.ca.gov>

SAN CA (USA) < derek.j.robinson1@navy.mil>; Liscio, Matthew P CIV USN NAVSEA DET RASO VA (USA)

<matthew.liscio@navy.mil>

Subject: N62473-17-D-0006 CTO: N6247318F5065 Parcel G - Soil Data Package TU-107

Dear Wayne, Nina and Terry,

To support the agencies oversight/split sampling effort and as a curtesy of information sharing, attached you will find the Soil Data Package for Parcel G Phase 1 TU-107.

Please let me know if you have any questions.

Very Respectfully,

Liz Roddy
Remedial Project Manager
NAVFAC BRAC PMO West
33000 Nixie Way
Bldg. 50, Floor 2
San Diego, CA 92147
(619) 524-5755
elizabeth.roddy@navy.mil